

FIRST RE-ESTABLISHMENT
GCDB 500440

SPECIAL CORNER

Quarter corner common to Sections 14 and 15, Township 32 South, Range 1 West, W.M.

Found at the proportioned position, exposed 2 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the BLM in 1958, marked:

T32S R1W
¼
S15 | S16
1958

Bearing trees recorded by the BLM in 1958, found with healed single blazes and measured to center at base:

- Sawed rotted Fir stump 30 ins. diam. brs. N 29° E, 48.8 ft. Record; N 44½° E.
- W. Fir 27 ins. diam. brs. S 25° W, 64.0 ft. Record; S 47° W.

Bearing trees of unknown origin found with healed blazes and measured to center at base:

- W. Fir 10 ins. diam. brs. N 86° E, 20.5 ft. record; (per tag) N 84° E.
- D. Fir 28 ins. diam. brs. record; S 40° W, 67.5 ft. (per tag)

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. Fir 11 ins. diam. brs. N 47¾° W, 4.0 ft.

Corner lies approx. N 78° E, 130 ft. from tag on 20 ins. diam. sawed B. Oak stump on west side of old spur road.

May 15, 2012
H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 184
V. – 15°30'