

FIRST RE-ESTABLISHMENT

GCDB 440700

Quarter section corner on the Township line Section 34 Township 33 South, Range 1 West and Section 3, Township 34 South, Range 1 West.

Found mound of stone and remains of old stake beneath the surface of the ground for corner.

From which:

- The remains of the stumps agree with the original BTs;
- Also the remains of the stump of the Pine BT as described by myself February 1, 1928.

Replaced old stake in mound of stone with a 1"x 36" galvanized iron pipe set 30" in the ground for corner from which:

- A 6" White Oak scribed CS-BT bears North 23° West, 68.8 feet;
- Scribed a 12" White Oak CS-BT which bears South 50¼° East, 55.2 feet.

June 27, 1950
C. Z. Boyden
L. D. Pinkham

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440700

The one quarter corner common to Section 34, Township 33 South, Range 1 West and Section 3, Township 34 South, Range 1 West, W.M.

Found flush, the 1x36 ins. iron pipe reported set on First Re-establishment, page 10, in 1950. Replace said pipe with a 1x36-inch Galvanized iron pipe, 32 ins. in the ground.

In the top of set pipe, set in concrete, a 2½-inch diameter brass cap marked:

T33S R1W
34
¼S —
3
C.S.
T34S
1986

Stump hole, with pine remains including reverse impressions of scribe marks and chaining notch lying alongside, bears Record: S87°E, 50.2 feet to estimated position of original face.

Bearing trees marked on First Re-establishment found:

- A White Oak, now 16-inch diameter with double healed blazes, bears Record: S50¼°E, 55.80 feet to center of tree at lower blaze.
- A White Oak, now 8-inch diameter with double healed blazes, bears record N23°W, 68.8 feet to center of tree at lower blaze.

Corner lies in an opening, on the South edge of an East-West jeep road, and on a down wire fence, course East.

September 29, 1986
D. Edwards
T. Newcomb

Edward McGinty
County Surveyor

V = 18°
P.-259

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 440700

Quarter corner common to Section 34, Township 33 South, Range 1 West, and Section 3, Township 34 South, Range 1 West, W.M.

Found missing from the corner position, the 1x36-inch Galvanized iron pipe with 2½-inch diameter brass cap reported as set on the Second Re-establishment, in 1986.

Set, at the corner position, a 1x36-inch Galvanized iron pipe, 6 ins. deep, with a 2½-inch diameter brass cap marked:

T33S R1W
34
¼S —
3
T34S
C.S.
1989

The single remaining original bearing tree recorded by Ives and Hyde in 1854, now a stump hole with pine remains, including reverse impressions of scribe marks and chaining notch lying alongside, bears S87°E, 50.2 feet to estimated face.

Bearing trees recorded as marked on First Re-establishment in 1950 found:

- A White Oak, now 17-inch diameter with double healed blazes, bears S50¼°E, 55.80 feet to center of tree at lower blaze.
- A White Oak, now 9-inch diameter with double healed blazes, bears Record: N23°W, 68.8 feet to center of tree at lower blaze.

Corner lies in an opening, on the South edge of an East-West jeep road and at a down wire fence, course East.

August 1, 1989
H. Durkee, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

V = 18°
P.-166