

FIRST RE-ESTABLISHMENT

GCDB 240100

Quarter corner common to Section 32, Twp. 34 South, Range 2 East and Section 5, Township 35 South, Range 2 East, W.M. $V = 21\frac{1}{2}^\circ$

Set 1x36-inch G.I. pipe 29 ins. in the ground with a $2\frac{1}{2}$ ins. bronze disc marked:

Jackson County 1976
T34S R2E
32
 $\frac{1}{4}$ S —
5
T35S

From which, original BTs recorded by N. Ford in 1855 found as follows:

- Down and rotted Oak snag, 18 ins. diam., containing evidence of old axe work, the stump hole and root remains of which bears $N43^\circ E$, 66.66 feet Record, $N40^\circ E$, 66.66 feet.
- A rotted Black Oak stump, about 28 ins. diam., bears record $S67^\circ W$, 33.0 feet to estimated face.

I mound stones around corner, marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- Cedar, 6-inch diameter, bears $N2\frac{1}{2}^\circ E$, 33.25 feet.
- Douglas Fir, 18-inch diameter, bears $S60^\circ W$, 27.13 feet.

May 4, 1976

B. Malotte

R. Frost

Witness:

A. Rambo, Medco Corp.

K. Bradshaw, Medco Corp.

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 240100

Quarter corner common to Section 32, Township 34 South, Range 2 East, and Section 5, Township 35 South, Range 2 East, W.M.

Found the 2½-inch diameter brass cap marked:

JACKSON COUNTY 1976
T34S R2E
32
¼S —
5
T35S

Set on the First re-establishment, dated 1976, protruding 6 ins. above ground in a small mound of stone from which:

Bearing trees marked on the First re-establishment found and measured to the center of tree at lower blaze:

- Incense Cedar 10-inch diameter, with healed blazes, bears record N02½°E, 33.25 feet.
- Fir stump 21-inch diameter and 5 feet high, with healed blazes, bears record S60°W, 27.13 feet.

Take new references:

- Douglas Fir 14 ins. diam. scribed "CS BT" on a double blaze brs. S69¼°E, 20.85 feet to center at lower blaze.
- Douglas Fir 5 ins. diam. scribed "CS BT" on a double blaze brs. S13½°E, 7.80 feet to center at lower blaze.
- Aluminum fence post protruding 4 feet above ground brs. N70½°W, 5.78 feet.

Corner lies approximately 250 feet Northeast of Butte Falls Highway in recent logging.

December 4, 1989
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 19°
p.-245

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT
GCDB 240100**

Quarter corner common to Section 32, Township 34 South, and Section 5, Township 35 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st Re-establishment in 1976, marked:

JACKSON COUNTY 1976
T34S R2E
32
¼S —
5
T35S

Bearing trees recorded on said 1st Re-establishment, found with healed double blazes and measured to center at lower blaze:

- Cedar, now 18 ins. diam. brs. record; N2½°E, 33.3 ft.
- Rotted Fir high-stump brs. record; S60°W, 27.1 ft.

Bearing trees recorded on 2nd Re-establishment in 1989, found and measured to center at lower blaze:

- D. Fir, now 20 ins. diam. with healed double blazes brs. record; S69¼°E, 20.9 ft.
- D. Fir, now 13 ins. diam. with healed single blaze, brs. S14½°E, 7.8 ft. record; S13½°E.

Aluminum fence post brs. record; N70½°W, 5.8 ft.

Marked new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:
P. Pine 6 ins. diam. brs. S80¼°W, 35.7 ft.

Corner lies approx. 250 ft. north of Butte Falls Hwy.

October 24, 2011
H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 65
V. – 17°40'