

FIRST RE-ESTABLISHMENT

ANGLE POINT

GCDB 700233

Angle point common to Section 25 of Township 34 South, Range 2 East and Section 30 of Township 34 South, Range 3 East, W.M.

Found at corner position , exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set the BLM in 1970 and marked:

T34S
AP1
R2E R3E
S25 | S30
1970

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found and measured to center at base;

- Cedar rotted high stump brs. S63°E, 5.6 ft. record; 4.6 ft. to face.
- D. fir rotted remains brs. N82°W, 11.5 ft. to center of stump hole, record; 10.6 ft. to face.

Bearing tree recorded by the BLM in 1970 found with a healed single blaze and measures to center at base;

- D. fir rotted high stump brs. record S19°W, 19.5 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 9 ins. diam. brs. N28¼°W, 10.4 ft.
- W. fir 16 ins. diam. brs. N40½°E, 18.3 ft.
- W. fir 8 ins. diam. brs. S65°W, 25.9 ft.

Only large trees in south-east quadrant.

Corner lies approx. 300 ft. north of end of blocked 4-wheel drive road.

January 12, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 10

V. – 12°55'