

FIRST RE-ESTABLISHMENT

GCDB 300100

Section corner, Northwest corner Section 4, Township 36 South, Range 2 West.

Found the witness trees in section 5, Township 36 South and the tree in section 33, Township 35 South intact.

Located corner and drove ¼" gas pipe for corner.

April 2, 1914
A.T. Brown, Deputy County Surveyor
H. Ling, Chainman
Philo Murphy, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 300100

Second Re-establishment of Section corner on Township line Sections 32 and 33, Twp. 35 S., R. 2 W. and sections 4 and 5, Twp. 36 South, Range 2 West.

Found the dead BT in Section 33 also stump of BT in Section 5, no evidence of pipe set by surveyor A.T. Brown April 2, 1914.

Set a 2" x 30" galvanized iron pipe 5" below the surface of the county road for corner

From which:

- A 20" White Oak scribed C.S.-BT bears S.41½°W., 631.8 feet,
- Scribe a 30" White Oak C.S.-BT which bears N.10½°E., 439.2 feet.
- Set a 1" x 32" galvanized iron pipe 22" in the ground which bears South 25.0 feet.
- Set a ¾" x 14" iron pin which bears N.45°W., 35.4 feet.

November 9, 1946
C. Z. Boyden
L. D. Pinkham

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 300100

Section corner common to Sections 32 and 33, Twp. 35 South, Range 2 West, W.M. and Sections 5 and 4, Twp. 36 South, Range 2 West, W.M.

Found 10 ins. below the asphalt surface of road, the 2 ins. diam. iron pipe set by C. Z. Boyden on second re-establishment, page 15, in 1946.

References recorded on second re-establishment found as follows:

- A $\frac{3}{4}$ ins. diam. G.I. pipe, found projecting 14 ins. and bent, bears South, 25.17 feet to center of pipe at ground level. Record: South, 25.00 feet.
- A $\frac{3}{4}$ ins. diam. square head iron bolt, found 15 ins. deep, brs. N45°47'W, 35.46 feet. Record: N45°W, 35.4 feet.
- White oak bearing trees marked in 1945, bear as recorded; N10½°E & S41½°W, to healed upper blazes. No measurements taken.
- A found $\frac{3}{4}$ ins. diam. smooth iron pin (disturbed) brs. N44°43'E, 41.84 feet. Reference survey 5819.

I set a 1 x 36 ins. G.I. pipe, 28 ins. in the ground (on East-West fence line) which brs. S45°47'E, 33.66 feet.

IN MON CASE
County B.C.I.P.

January 23, 1979
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 300100

Section corner common to Sections 32 and 33, Township 35 South, Range 2 West, W.M. and Sections 5 and 4, Township 36 South, Range 2 West, W.M.

Found 2½ ins. diam. brass cap under asphalt in monument case, cap marked:

T35S R2W

32 | 33

5 | 4

T36S

1979

Removed existing monument case and replaced with a new case over the undisturbed 1979 brass cap.

Reference recorded on Third Re-establishment, dated 1979, found:

- ¾ in. smooth iron pin exposed 3½ ins., located 0.5 feet south of fence post corner to North-South and East-West (bending South Westerly) bearing fence lines, bears record N44°43'00"E, 42.20 feet. Record distance 41.84 feet.

Set new references:

- 5/8 x 24 ins. rebar with 2 ins. diam. aluminum cap marked "Jackson County Surveyor" flush with the ground:
 1. Located 15 feet south of the edge of Tresham Ln. and 27 feet west of the center of driveway to residence No. 3657 Tresham Ln., bears S60°10'35"W, 52.13 feet.
 2. Located 15 feet north of the edge of Tresham Ln. and 6 feet west of Duggan Rd. Stop Sign, bears N57°10'26"W, 46.66 feet.

Corner lies near the centerline intersection of Tresham Ln. with Duggan Rd.

May 27, 2016

L. Madden

J. Hall

Scott Fein

Jackson County Surveyor