PROPORTIONED CORNER

GCDB 340100

Quarter Section corner on the Township line, Section 33, Township 35 South, Range 2 West and Section 4, Township 36 South, Range 2 West.

No evidence of the original BTs.

Set a 1" x 36" galvanized iron pipe $\frac{1}{2}$ foot below the surface of the County road for corner on single proportion distance between the first section corner to the East and West from which $\frac{1}{4}$ section corner:

- A 3/4" x 14" iron pin bears N.451/4 °W. 42.56 feet
- Scribe a 12" ash tree which bears \$.79½ °E. 273.8 feet,
- A nail in the Northwest base of power pole #4584 bears S.9°E. 30.72 feet.

November 9, 1946 C. Z. Boyden L. D. Pinkham

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

FIRST RE-ESTABLISHMENT GCDB 340100

Quarter corner common to Section 33, Twp. 35 South, Range 2 West and Section 4, Twp. 36 South, Range 2 West, W.M.

Found, 20 ins. below asphalt surface of road, the 1 ins. diam. iron pipe set by C. Z. Boyden (on proportionate measurement) in 1946. Reference: Jackson County Re-establishment (T35S) Book.

- A ¾ ins. diam. iron bolt (with nut) brs. as recorded by Boyden: N45¼°W, 42.56 feet.
- A Found, smooth iron pin, % ins. diam., projecting 1 ins. brs. S0°21'E, 30.00 feet. Reference: Survey No. 5363.
- A 2 ins. diam. black iron pipe, found 5 ins. deep, brs. S63°23'W, 66.91 feet. Reference: Survey No. 2127.
- A ¾ ins. diam. iron pin, found flush with the surface of the road brs. N89°59'15"W, 30.00 feet.

January 22, 1979 B. Malotte R. Frost Approved by: Edward McGinty County Surveyor

5/2/79 IN MON CASE County B.C.I.P. ALSO SEE RECORDED SURVEY NO. 2915

SEE NEXT PAGE FOR CORNER REPORT

CORNER REPORT

GCDB 340100

Quarter corner common to Section 33, Twp. 35 South, Range 2 West and Section 4, Twp. 36 South, Range 2 West, W.M.

Found a 3 ins. diam. brass cap in monument well marked:

Found references per First Re-establishment, dated 1979:

- 34 ins. diam. iron bolt 10 ins. below the ground bears N45°15′ 00″W, 42.58 feet. Record 42.56 feet
- ¾ ins. diam. iron pin flush with the asphalt at the intersection of Wheeler Rd. and Tresham Ln. bears S 89°58′22″ W, 29.99 feet. Record: N89°59′15″W, 30 feet
- 5% ins. diam. smooth iron pin flush with ground approximately 1.5 feet west of fence post corner and approximately 4.5 feet Southwest from Power Pole No. B-11951 bears \$0°05'57"E, 29.94 Record: \$0°21'E, 30 feet
- 2 ins. diam. iron pipe 2 ins. below ground with nail in center located approx. 1 foot south of North-South bearing fence post corner, pipe falls under said fence, bears \$63°19'47"W, 66.87 Record: \$63°23'W, 66.91.

Corner falls in center line of Tresham Ln. approximately 30 feet east of the intersection of Wheeler Rd. and Tresham Ln. and approximately 15 feet South of Power Pole No. B-32851.

Note: Replaced monument well lid.

May 11, 2016

L. Madden

Scott D. Fein

J. Hall

Jackson County Surveyor