PROPORTIONED CORNER - NO FIRST RE-ESTABLISHMENT GCDB 100400

Section Corner on Willamette Meridian, Sections 13 and 24, Township 36 South, Range 1 West and Sections 18 and 19, Township 36 South, Range 1 East.

Set a 2" x 32" iron pipe 4" below the surface of the road for corner on single proportion distance,

From which:

- An 8" White Oak scribed CS-BT bears N20¾°E, 284.3 feet.
- Scribed a 12" White Oak CS-BT which bears \$73\% °E, 270.7 feet.
- Scribed a 28" White Oak CS-BT which bears \$27\% °W, 450.2 feet.
- Scribed a 5" White Oak CS-BT which bears N45½°W, 66.7 feet.

April 6, 1945 C. Z. Boyden L. J. Shorey R. E. Welch F. Foley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT GCDB 100400

Section corner common to Sections 13 and 24, Township 36 South, Range 1 West, and Sections 18 and 19, Township 36 South, Range 1 East, W.M.

Found, 12 ins. below the asphalt surface of Meridian Road, the 2 ins. diam. iron pipe, set by proportion method for the corner as recorded in Jackson County re-establishment book, Township 36 South, Range 1 East, in 1945.

To perpetuate this position I set a 1 \times 20 ins. G.l. pipe inside found pipe 4 ins. below the road surface in concrete with $2\frac{1}{2}$ ins. diam. bronze disc marked:

From which:

- The single remaining bearing tree recorded in 1945, a White Oak, now dead, 28 ins. diam., with healed blazes, brs. S27°45'W, (basis of bearings), 451.8 feet to center of tree. Record; S27¾°W, 450.2 feet.
- I mark "CS" "BT" the Southwesterly tree, 11 ins. diam., of a clump of (yellow) Apple Trees which brs. N36°37'E, 222.83 feet to center of tree at lower blaze.
- Near the base of a 3½ x 50 ins. iron (pipe) post I mark:

Said mark brs. N87°05'E, 37.58 feet.

- A railroad spike marked "RP 1980" in a 12 ins. square wood post corner of North-South and West bearing fence lines, brs. S88°48'W, 24.40 feet.
- A % x 30 ins. re-bar with yellow plastic cap marked "JACKSON C.S." flush with the ground, on North-South fence line brs.N21°35'W, 65.00 feet.

January 24, 1980 J. Swanson R. Frost Approved by: Edward McGinty County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT GCDB 100400

Section corner common to Sections 13 and 24, Township 36 South, Range 1 West, and Sections 18 and 19, Township 36 South, Range 1 East, W.M.

Fd., 6 ins. below the asphalt surface of Meridian Road, the top of iron pipe set by proportion method for the corner in 1945. The brass cap set on the Second Re-establishment, dated 1980, is missing and the top of pipe Is extremely damaged by previous road grinding for resurfacing.

To perpetuate this position set a 2½ ins. diam. brass cap mkd.:

In cement over found pipe flush with the road surface.

From which, Second Re-establishment references found:

- Punch mark and marks 1980 RP near the base of a 3½ ins. diam. pipe fence post brs. Record N87°05′00″E, 37.64 ft. Record distance 37.58 ft.
- A center punched railroad spike marked RP 1980 set near base of a 12 ins. square fence post of North-South and west bearing fence lines brs. S89°02′29″W, 24.47 ft. Record S88°48'W, 24.40 ft.
- 5%-ins. diam rebar with broken yellow plastic cap flush with the ground brs. N21°27′39″W,
 65.00 ft. Record bearing N21°35'W.

New reference:

• Set %-ins. x 24 ins. rebar with 2 ins. diam. aluminum cap marked:

'JACKSON COUNTY SURVEYOR'

protruding 1 in. above ground in the easterly graveled shoulder of Meridian Rd. brs. $514^{\circ}59'55''E$, 70.72 ft.

Corner is located near the center of the paved surface of Meridian Rd.

July 29, 2010 S. Beecher Kerry K. Bradshaw County Surveyor P.-41 Series II Book I