

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 6 ONLY
GCDB 140700**

Standard Quarter corner on the North boundary of Section 6, Township 36 South, Range 1 East, and being on the Eighth Standard Parallel South.

Found the 5/8" iron pin set for corner on Recorded Survey No. 2920. Set a 1" x 36" galvanized iron pipe over said 5/8" iron pin, 28" in the ground, with a 2 1/2" bronze cap stamped:

T. 36 S. R. 1 E.
1/4 S — Cor.
6
C.S.
1971

From which:

- A 1" galvanized iron pipe with 2 1/2" bronze cap located at the South Quarter corner to Section 31, Township 35 South, Range 1 East bears East, 72.60 feet.
- The original bearing tree (now a 16" White Oak in good condition with a portion of the "1/4" scribe visible) bears S58 1/2°E, 26.4 feet to the face of the upper blaze (original record: 10" White Oak S58°E, 26.4 feet).
- The original bearing tree, (now a 16" broken off Ash snag with rotted out faces) bears N8°W, 53.5 feet to the face of the upper blaze (original record: 8" White Ash, N8°W, 53.5 feet).

Mark a new tree as follows:

- A 16" White Oak scribed "CS-BT" bears S22 3/4° W, 29.3 feet to the face of the lower blaze.

January 19, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve