

FIRST RE-ESTABLISHMENT

GCDB 500400

Section corner common to Sections 14, 15, 22 and 23, Township 36 South, Range 1 East, W.M.

From the following evidence at the location described below, set a 1x30 ins. flanged galvanized iron pipe 24 ins. in the ground (which falls on the south side of a found mound of stone) with 2½ ins. diam. attached brass cap marked:

JACKSON COUNTY SURVEYOR

T36SR1E

15 | 14

—|—

22 | 23

1993

UNLAWFUL TO DISTURB

Original bearing trees recorded by Ives and Hyde in 1854 found:

- Stump hole with the rotted oak remains alongside, containing chaining notch and scribe mk. "B" on axed face brs. Record: S15°E, 101.64 feet slope distance to estimated face.
- Black Oak, 16 ins. diam. hollow, brs. N7°W, 32.34 feet to estimated face. Record; N10°W.
- Stump hole with rotted oak shell alongside, brs. Record: S86°W, 39.96 feet to estimated face.
- No trace of the NE bearing tree.

Marked new trees "CS" "BT" and take measurements to the center of tree at lower blaze:

- Ponderosa Pine, 16 ins. diam., brs. S23½°E, 31.35 feet.
- Ponderosa Pine. 11 ins. diam., brs. S74°W, 19.50 feet.
- Ponderosa Pine, 15 ins. diam., brs. N25°W, 53.05 feet.
- White Oak, 5 ins. diam., brs. N25½°E, 36.90 feet.

Corner lies on north-south fence line.

February 24, 1993
T. Newcomb, Tech.
J. Burgess, Tech.

Verlyn Thomas
County Surveyor

V = 16½°

P. -26