

**GCDB 100540**

Quarter corner common to Section 7, Township 36 South, Range 3 East, and Section 12, Township 36 South, Range 2 East, W.M.

**SEE RECORDED SURVEY NO. 2577, also No. 3323**

**SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT**

**FIRST RE-ESTABLISHMENT**  
**GCDB 100540**

**SPECIAL CORNER**

Quarter corner common to Section 12, Township 36 South, Range 2 East and Section 7, Township 36 South, Range 3 East, W.M.

Monument set by the BLM in 1963, destroyed by road construction. Found at the proportioned position, 7 ins. deep, the  $\frac{5}{4}$  in. diam. rebar with a  $1\frac{1}{2}$  ins. diam. aluminum cap set on Survey No. 3323 in 1966, marked:

R.S. 461  
12 | 7  
 $\frac{1}{4}$

- Bearing tree recorded by the BLM in 1963, a W. Fir, now 20 ins. diam. with a healed single blaze, brs. record;  $S62\frac{1}{2}^{\circ}W$ , 59.4 ft. to center at base.
- Bearing tree recorded on Survey No. 3323, a Cedar, now 31 ins. diam. with healed single blaze, brs. record;  $N40^{\circ}E$ , 81.8 ft. to center at base.

**Note:** The view to both of these existing bearing trees is now obstructed by new-growth trees.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 9 ins. diam. brs.  $N14^{\circ}W$ , 27.1 ft.

Corner lies at the westerly toe-of-slope of a "pumper" pond and approx. 70 ft. west of gravel logging road.

June 27, 2012

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 209

V. –  $12^{\circ}30'$