

FIRST RE-ESTABLISHMENT

GCDB 340100

Quarter corner common to Section 33, Township 36 South, and Section 4, Township 37 South, Range 3 East, W.M.

Found at the corner position, exposed 8 ins. in a mound of stones and abutted to a steel fence corner post, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1961, marked:

T36S R3E
S33
¼—
S4
T37S
1961

Bearing trees recorded by R.S. 404 (date unknown) found with healed single blazes and measured to center at base:

- Cedar now 15 ins. diam. brs. record; N68°W, 36.3 ft.
- Cedar now 23 ins. diam. brs. S37°W, 28.0 ft. record; 29.0 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 6 ins. diam. brs. N5°E, 11.7 ft.

Corner lies approx. 200 ft. southeasterly along private driveway from Hwy. 140, then south approx. 60 ft. at fence corner, fence brs. east and south.

*Due to proximity of fence corner post and steel fence post with a sign, hand compass was used.

February 4, 2009

H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 26
V. – 19° (hand
compass)