

FIRST RE-ESTABLISHMENT

GCDB 600100

Section corner common to Sections 35 and 36 of Township 36 South, and Sections 1 and 2 of Township 37 South, Range 3 East, W.M.

Found at the corner position, exposed 2 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1961 and marked:

T36SR3E
S35 | S36
—+—
S2 | S1
T37S
1961

Single remaining original bearing tree recorded by Wm. Turner of the GLO in 1882 found and measured to center at base;

- Fir high stump with a partially healed blaze with rotted face brs. record S40°E, 33.0 ft.

Bearing trees recorded by the BLM in 1961 found with healed single blazes and measured to center at base;

- D. fir rotted stump brs. record N64°E, 23.8 ft.
- D. fir now 20 ins. diam. brs. record S11°E, 90.4 ft.
- D. fir now 33 ins. diam. brs. S45½°W, 25.7 ft. record; S44°W.
- D. fir 24 now ins. diam. brs record N9°W, 26.4 ft.

Marked new bearing tree 'CS''BT' and measured to center at lower blaze;

D. fir 14 ins. diam. brs. S76°E, 24.6 ft.

No suitable trees in North-East quadrant

Corner lies approx. 25 ft. north of gravel road.

November 2, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -248

V. - 15°30'