

FIRST RE-ESTABLISHMENT
GCDB 600140

SPECIAL CORNER

Quarter corner common to Sections 35 and 36 of Township 36 South, Range 3 East, W.M.

Found at the proportioned corner position , exposed 8 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by Harold Center on Survey# 7978 in 1976 and marked:

T36S R3E
¼
35 | 36
1979
LS 1071

Bearing trees recorded on Survey# 7978 in 1979 found with healed double blazes and measures to center at base;

- D. fir now 18 ins. diam. brs. N60½°W (as indicated by tag), 18.5 ft. record; N50½°W.
- D. fir dead, down, and rotted brs. record; N22½°E, 26.1 ft. to center of root hole.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 7 ins. diam. brs. S13½°E, 26.2 ft.
- D. fir 11 ins. diam. brs. S82½°W, 12.4 ft.
- Mt. McLaughlin brs. N57°E to peak.
- No suitable trees in the North-East quadrant

Corner lies approx. 150 ft. Northerly of intersection of paved and dirt roads.

November 3, 2009
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 249
V. – 14°