

FIRST RE-ESTABLISHMENT

GCDB 500700

Corner common to Sections 34 and 35, Township 35 South, Range 4 West and Sections 2 and 3, Township 36 South, Range 4 West.

- Found a $\frac{3}{4}$ " iron pipe 3" below the surface of the County road for corner.
- Also found a 24" White Oak with the Northerly face chopped off which bears South 2° East 70.3 feet to the center of the tree.

Replaced the $\frac{3}{4}$ " pipe with a 1"x36" galvanized iron pipe with a $2\frac{1}{2}$ " bronze cap set 3" below the surface of Earhart Road for corner, said cap stamped:

T35&36S, R4W	
Section Cor.	
34	35
----- c.s.	
3	2
1965	

From said pipe corner, I establish the following new witness trees:

- Scribered a 12" Yellow pine "CS-BT" which bears North 39° East, 89.5 feet to the face of the lower blaze;
- The Northeast corner of a concrete block wall house bears North 45° West, 141.16 feet;

The center of a 2" pipe, roof support at the Northeast corner of a carport, bears South $35\frac{1}{4}^{\circ}$ West, 62.0 feet.

November 23, 1965
Lee D. Pinkham, Deputy County Surveyor
L. W. Hart

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 500700

Section corner common to Sections 34 and 35, Township 35 South, Range 4 West and Sections 2 and 3, Township 36 South, Range 4 West, W.M.

Found 8 ins. deep in center of paved road, unrecorded brass cap marked properly except for the date of 1971 and the markings below the date "control monument". The re-establishment was done in 1965.

Set a 2½ ins. diam. brass cap flush with pavement over found brass cap in concrete marked:

T35S R4W	
34	35
—	
3	2
C.S.	
T36S	
1991	

All accessories reported on first re-establishment still in good condition.

January 21, 1991
T. Newcomb, Tech.
H. Durkee, Tech.

Verlyn Thomas
County Surveyor

P.-5