

FIRST RE-ESTABLISHMENT

CORNER COMMON TO SECTIONS 32 AND 33 ONLY

GCDB 300100

Corner common to Sections 32 and 33 on the South boundary of Township 38 South, Range 1 West.

Found a $\frac{5}{8}$ " iron pin for corner. Drove a 1"x 36" galvanized iron pipe directly over said pin, 28" in the ground with 2½" bronze cap stamped:

T38 - 39S, R1W
Sec. 32 | 33 Cor.
—|—
5
C.S.
1967

From which:

- The original bearing tree, now a 24" fir stump, plainly scribed bears N65°W, 13.9 feet to the face of the lower blaze. Record: N61°W, 13.9 feet.
- The original bearing tree, now a 24" fir, plainly scribed, bears S14°W, 19.1 feet to the face of the upper blaze.
- Also found parts of rotted stumps of the Southeast and Northeast bearing trees both of which check for location.
- A 20" Fir, scribed "CS-BT" bears N39°E, 27.5 feet to the face of the lower blaze;
- A 20" Fir, scribed "CS-BT" bears N35°W, 35.0 feet to the face of the upper blaze;
- A 16" Fir, scribed "CS-BT" bears N83½°E, 35.2 feet to the face of the lower blaze.

December 22, 1967
L. D. Pinkham, Deputy County Surveyor
Gary Kaiser

ADDENDUM

Found at the corner position, exposed 6 ins., the brass cap monument set on 1st Re-establishment in 1967 in good condition.

All bearing trees recorded on said Re-establishment found in good condition with healed blazes, except the original fir stump to the northwest which is deteriorating.

Corner lies approx. 250 ft. south of Anderson Cr. Road on 60% slope.

March 4, 2009
H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 49