

FIRST RE-ESTABLISHMENT

GCDB 100600

Section corner common to Sections 1 and 12, Township 39 South, Range 2 East and Sections 6 and 7, Township 39 South, Range 3 East, W.M.

Found at the proportioned position, exposed 8 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1961, marked:

T39S
R2E R3E
S1 | S6
—+—
S12 | S7
1961

Bearing trees recorded by the BLM in 1961, found with healed single blazes and measured to center at base:

- Fir, dead and down, brs. record; S53°E, 21.0 ft. to center of stump hole.
- Fir snag, 30 ins. diam. brs. record; S71°W, 18.5 ft.
- Sawed fir stump 18 ins. diam. brs. record; N41°W, 50.8 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. fir 8 ins. diam. brs. N25¾°E, 36.3 ft.
- W. fir 9 ins. diam. brs. S48½°E, 10.9 ft.
- W. fir 8 ins. diam. brs. S77¼°W, 44.0 ft.
- W. fir 10 ins. diam. brs. N30°W, 45.3 ft.

Corner lies approx. N50°W, 550 ft. from bend in 4-wheel drive spur road and 2 ft. west of north-south fence line.

June 9, 2010

H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. – 134

V. – 14°05'