

FIRST RE-ESTABLISHMENT

GCDB 500500

Section corner common to Sections 10, 11, 14 and 15, Township 39 South, Range 3 East, W.M.

At the corner found projecting 9 inches, a 12 x 13 x 16-inch stone with a small "+" at the top in a mound of stone.

Replaced found stone with and deposited alongside a 1 x 36-inch Galvanized iron pipe 30 inches in the ground with a 2½-inch diameter brass cap marked:

T39S R3E	
10	11
— —	
15	14
C.S.	
1992	

Original bearing trees recorded by Sewall Truax in 1859 found:

- Fir sawed stump, 47-inch diameter, with rotted lower blaze, bears N86°28'E, 1043.80 feet to face. Record: N87°E, 950.40 feet.
- Stump hole of a down Pine, 28-inch diameter, containing scribe marks "T39S" "BT" on opened face bears S31°51'E, 323.40 feet to estimated face. Record: S29¼°E.
- Rotted pine snag, 21-inch diameter, bears S13°03'W, 337.50 feet to center of tree. Record: S14°W, 340.56 feet.
- Found rotted remains and axe work, near stump hole, bears N0°32'W, 860.00 feet. Record: N0°15'W, 863.28 feet.
- Witness corner bears S0°27'59"E, 603.88 feet.

Corner lies in Hyatt Reservoir.

October 12, 1992
T. Newcomb, Tech.
J. Burgess

Verlyn Thomas
County Surveyor

P.-86

SEE Job File No. 92-7.