

FIRST RE-ESTABLISHMENT

GCDB 500600

Section corner common to Sections 2, 3, 10 and 11, Township 39 South, Range 3 East, W.M.

Found stump of Southeast BT with the BT scribe legible. The Northwest BT with old scars, but not opened. Also the Northeast BT with old axe marks:

From which evidence:

- Set a 2" x 36" galvanized iron pipe 28" in the ground for corner.

From which:

- A 7" White Fir scribed CS-BT bears N51½°E, 59.3 feet.
- Scribe an 8" White Fir CS-BT which bears S54°E, 44.4 feet.
- Scribe a ____ lodge pole pine CS-BT which bears North 61.7 feet.
- Scribe an 18" lodge pole pine CS-BT which bears N54°E, 81.6 feet.

Corner falls near the highway surface of Hyatt Prairie Reservoir.

August 19, 1955
C. Z. Boyden
John C. Warnkee

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 500600

Section corner common to Sections 2, 3, 10 and 11, Township 39 South, Range 3 East, W.M.

Found projecting 6 inches, the 2-inch diameter iron pipe, set on First re-establishment, in 1955.

In the top of found pipe, set a 2½-inch diameter brass cap marked:

T39S	R3E
3	2
10	11
C.S.	
1986	

No evidence of original bearing trees could be found.

Bearing trees marked on First Re-establishment found and measured to center of trees at lower blaze:

- Lodgepole Pine, 17-inch diameter, with healed blazes (facing S45°E), bears North, 61.85 feet. Record: 61.7 feet.
- White Fir, 22-inch diameter, with healed blazes, (facing South) bears N48°30'E, 59.15 feet. Record: N51½°E, 59.3 feet.
- The (Pine) Northeast BT and the Southeast BT are now gone.

Marked a new tree "CS" "BT":

- Lodgepole Pine, 6-inch diameter, bears S72°E, 1.80 feet to center of tree at lower blaze.
- The Northwest corner of concrete foundation of wood frame cabin, bears N42°08'E, 77.67 feet.
- A found 1-inch diameter iron pipe (flush), bears N45°W, 0.25 feet (origin unknown).

Corner lies 9 feet N45°E, from the (visible) high water line of Hyatt Lake.

August 6, 1986
R. Frost
T. Newcomb

Edward McGinty
County Surveyor

V = 18½°
P. -234

SEE NEXT PAGE FOR CORNER REPORT

CORNER REPORT
GCDB 500600

Section corner common to Sections 2, 3, 10 and 11, Township 39 South, Range 3 East, W.M.

Fd. projecting 5 ins., the 2½ ins. diam. brass cap mkd:

T39S R3E
3 | 2

10 | 11
C.S.
1986

Bearing tree mkd. on First re-establishment fd. and measured to center of tree at lower blaze:

- Lodgepole Pine, 19 ins. diam., with healed double blaze (facing S45°E), brs. record bearing, 62.20 ft.; Record 61.85 feet.

Bearing tree mkd. on Second re-establishment fd. And measured to center of tree at lower blaze:

- Lodgepole Pine, 6 ins. diam., brs. record bearing and distance.

Fd. 1 in. diam. iron pipe (flush), brs. N45°W, 0.25 ft. (origin unknown).

Cabin from 1986 re-establishment is gone, and a newer home has been built.

Corner lies in wooded area near the (visible) high water line of Hyatt Lake.

August 20, 2015
B. Paull
J. Hall

Scott Fein
County Surveyor

V-
P. 11-12