

## FIRST RE-ESTABLISHMENT

GCDB 540700

Quarter corner common to Section 35, Township 38 South, Range 3 East, and Section 2, Township 39 South, Range 3 East, W.M.

Found both original witness trees, with scribe marks plain.

Set a 1" x 36" galvanized iron pipe with bronze cap stamped:

T38 & 39 S R3E  
35  
¼S — Cor.  
2  
C.S.  
1962

30" in the ground for corner.

From which:

- The original witness tree (now a rotted Fir stump) bears N30½°E, 20.7 feet.
- The original witness tree (now a 27" Fir) bears S39½°W, 20.7 feet.
- Scribed a 6" Fir, CS-BT, which bears N31°E, 19.4 feet.
- Scribed a 6" Fir, CS-BT, which bears S80½°E, 26.4 feet.

October 31, 1962  
F. A. Roberts  
L. Hart  
J. Dressler

Approved by:  
M. E. Boyden,  
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 540700

Quarter corner common to Section 35, Township 38 South, Range 3 East and Section 2, Township 39 South, Range 3 East, W.M.

Found projecting 3 inches, in a ring of stones, the 2½-inch diameter brass cap marked:

T38 + 39S R3E  
35  
¼S — Cor.  
2  
C.S.  
1962

On a 1-inch diameter galvanized iron pipe as reported set in First Re-establishment, page 5, in 1962.

Original bearing tree marked by Sewell Truax in 1859 found:

- White Fir, now 34-inch diameter with a scribed "s" visible in exposed upper face, bears Record: Per said First Re-establishment; S39½°W, 20.63 feet to said face.

Bearing tree marked on said First Re-establishment found:

- White Fir, now 12-inch diameter with double healed blazes, bears N30¾°E, 19.67 feet to center of tree at lower blaze. Record: N31°E, 19.4 feet.
- The other bearing tree was destroyed by a bulldozer.

Scribe a new tree "CS-BT":

- Cedar, 9-inch diameter, bears S15¾°W, 19.44 feet to center of tree at lower blaze.

Corner lies at the intersection of blazed lines bearing North and East at the east edge of a clearing, on nearly level ground and about 125 feet East of a dirt road c. North and South.

April 11, 1988  
D. Edwards, Tech.  
T. Newcomb, Tech.

Edward McGinty  
County Surveyor

V = 17°  
P. -122

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 540700

Quarter corner common to Section 35, Township 38 South and Section 2, Township 39 South, Range 3 East, W.M.

Found at the corner position, exposed 3 inches and in a mound of stones, the 1-inch diameter galvanized iron pipe with a 2½-inch diameter brass cap set on First Re-establishment in 1962, marked:

T38 & 39S R3E  
35  
¼S —  
2  
C.S.  
1962

- Single remaining original bearing tree recorded by Sewall Truax in 1859, a White Fir, now 35-inch diameter with scribe mark "B" in opened lower blaze, bears S 39½° W, 20.8 feet. Record: 20.6 feet to center at base.
- Bearing tree recorded on First Re-establishment in 1962, a White Fir, now dead and leaning, bears N 30¾° E, 19.4 feet. Record: 19.7 feet to center at lower blaze.
- Bearing tree recorded on Second Re-establishment in 1988, a cedar, now 12-inch diameter with healed double blazes bears Record: S 15¾° W, 19.4 feet to center at lower blaze.

Marked new bearing trees "CS" "BT" and took measurements to center at lower blaze:

- White Fir 9-inch diameter bears S 25½° E, 12.3 feet.
- White Fir 9-inch diameter bears N 11½° E, 10.6 feet.

Corner lies approximately 150 feet east of old dirt Road.

September 27, 2006

H. Durkee  
B. Beeman

Roger R. Roberts  
Jackson County Surveyor

P. - 167  
V. - 15°50'