

FIRST RE-ESTABLISHMENT

GCDB 600700

Section corner common to Sections 35 and 36, Township 38 South, Range 3 East and Sections 1 and 2, Township 39 South, Range 3 East.

Determined the point for the corner by reference to two original bearing trees. At which point, I set a 2"x36" gas pipe to mark and perpetuate the corner.

From which:

- An 8" fir bears North 31°E, 17.2 feet (original).
- A 22" fir bears North 61°W, 15.2 feet (original).
- A 12" fir scribed "C.S.-BT" bears S69½°E, 27.8 feet.
- A 10" fir scribed "C.S.-BT" bears S26½°W, 35.1 feet.

July 16, 1938
L. E. Smith,
Deputy Surveyor

C. Bourne, Chainman
Walter Hartle, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600700

Section corner common to Section 35 and 36, Township 38 South, Range 3 East, and Section 1 and 2, Township 39 South, Range 3 East, W.M. $V = 20^\circ$

Found, projecting 18 inches in mound of stone, the 2-inch diameter, iron pipe set by L. E. Smith on First Re-establishment in 1938.

Original bearing trees marked by S. Truax in 1859 and noted by Smith found as follows:

- White Fir, 33-inch diameter, scribed "38S36" in exposed upper face bears $N31^\circ E$, 17.94 feet to center. Record: $N31^\circ E$, 17.16 feet.
- White Fir, 33-inch diameter, with axed into upper face, bears $N61^\circ W$, 16.41 feet to center. Record: $N61^\circ W$, 15.18 feet.
- Original SE and SW BTs now gone.

Bearing trees found by Smith:

- White Fir, 18-inch diameter with healed blazes, bears $S69\frac{1}{2}^\circ E$, 27.8 feet to center. Record: $S69\frac{1}{2}^\circ E$, 27.8 feet.
- Douglas Fir, 26-inch diameter, with healed blazes, bears $S27\frac{1}{2}^\circ W$, 35.37 feet to center. Record: $S26\frac{1}{2}^\circ W$, 35.1 feet.

I mark a new tree "CS BT":

- Douglas Fir, 15-inch diameter, bears $N82^\circ E$, 37.43 feet to center of tree at lower blaze.
- A metal fence post stands along South side of corner.

June 22, 1976
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 600700

Section corner common to Sections 35 and 36, Township 38 South, Range 3 East and Sections 1 and 2, Township 39 South, Range 3 East, W.M.

Found the 2-inch diameter galvanized iron pipe set on the First Re-establishment, dated 1938 protruding 18 inches aboveground in mound of stone.

Drove a 1-inch diameter galvanized iron pipe inside found pipe until both protrude 8 inches aboveground and set a 2½-inch diameter brass cap marked:

T38S	R3E
35	36
2	1
C S	
T39S	
1989	

In cement in the top of the 1-inch diameter pipe.

Original bearing trees marked by Truax in 1859 found:

- White Fir, 37-inch diameter, with opened upper blaze and "8S36" scribe visible, bears Record: N31°E, 17.9 feet to center of tree at lower blaze.
- White Fir, 34-inch diameter, with opened upper blaze and unmarked face, bears Record: N61°W, 16.4 feet to center of tree at lower blaze.

Bearing trees marked on the First Re-establishment found and measured to center of tree at lower blaze:

- White Fir, 20-inch diameter, with healed double blaze, bears Record: S69½°E, 28.0 feet.
- Douglas Fir, 29-inch diameter, with healed double blaze, bears S29°W, 35.1 feet. Record bearing S26½°W.

Bearing tree marked on the Second Re-establishment, dated 1976 found and measured to center of tree at lower blaze:

- Douglas Fir, 17-inch diameter, with healed double blaze, bears Record: N82°E, 37.7 feet. Record distance; 37.43 feet.

Corner lies in timber at corner of old clear cut approximately 700 feet North of Hyatt Lake - Howard Prairie Road.

September 18, 1989
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 19½°
P.-193

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 600700

Section corner common to Sections 35 and 36, Township 38 South, Range 3 East and Sections 1 and 2, Township 39 South, Range 3 East, W.M.

Fd. the 2 ins diam. galvanized iron pipe with 1 in. diam. galvanized iron pipe inside as set on the Third re-establishment, dated 1989, with 2½ ins. diam. brass cap mkd.:

T38S R3E
35 | 36
—+—
2 | 1
C S
T39S
1989

In the top of the 1 in. diam. pipe. protruding 6 ins. above ground. The brass cap is oriented East.

Original bearing trees marked by Sewell Truax in 1859 found;

- The Northeast bearing tree is dead and down with indeterminate position due to logging.
- The original Northwest bearing tree now a rotting stump with healed blaze brs. record N61°W, 16.4 ft. to center of stump.

First re-establishment, dated 1938, bearing tree found:

- Douglas Fir 33 ins. diam. with healed blazes brs. Third re-establishment record S29°W, 35.1 ft. to center of tree at lower blaze.

Second re-establishment, dated 1976, bearing tree found;

- Douglas Fir high stump 20 ins. diam. with healed blazes brs. N83°E, 37.7 ft. to center of stump at lower blaze. Record bearing N82°E.

Mark new trees 'CS BT' and measure to the center of tree at lower blaze;

- Douglas Fir 16 ins. diam. brs. S25°E, 41.9 ft.
- Ponderosa Pine 7 ins. diam. brs. N55°E, 88.9 ft.
- Incense Cedar 16 ins. diam. brs. N60°W, 92.8 ft.

Corner lies in logged area approx. 700 ft. North of Hyatt Lake - Howard Prairie Rd.

March 18, 2010

S. Beecher

S. Fein

Kerry K. Bradshaw

County Surveyor

V = 19½°

P.-33

Series II Book I