

FIRST RE-ESTABLISHMENT

GCDB 100200

Re-establishment of the Section corner on the Range line between Sections 30 and 31, Township 40 South, Range 3 West, W.M. and Sections 25 and 36, Township 40 South, Range 4 West, W.M.

- Found original BT, a 5" White Oak plainly scribed, to SW.
- Also 40" Yellow Pine blown down with scribe legible to SE:

From which evidence: Set a 2" x 36" galvanized iron pipe 34" in the ground for corner from which the original BT, a 5" White Oak bears S36°W, 20.46 feet.

- Scribed a 4" White Oak CS-BT, which bears N26°W, 40.0 feet.
- Scribed a 14" White Oak CS-BT, which bears N32°E, 75.7 feet.
- Scribed a 9" Fir, CS-BT, which bears S33°E, 94.9 feet.

December 15, 1939
C. Z. Boyden
C. I. Bourne
A. M. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 100200

Section corner common to Sections 30 and 31, Township 40 South, Range 3 West and Sections 25 and 36, Township 40 South, Range 4 West, W.M.

At the corner, found flush with the ground, the 2½-inch diameter iron pipe with 3-inch diameter standard BLM brass cap marked:

T40S	
R4W	R3W
S25	S30
S36	S31
1964	

As recorded by the BLM in 1964.

The single remaining bearing tree,

- A Douglas Fir, marked by the BLM in 1964, now 20-inch diameter, with healed single blaze bears S1°E, 47.55 feet to center. Record: 48.18 feet.

Take new references:

- U.S. Army Corps of Engineers control Station "AG 1", a brass cap in concrete pedestal located about 1900 feet distant, midway between the base and top of cut-bank of road on the Westerly side of Applegate Lake bears N68°10'W.
- In line with above-described monument, set 5/8 x 30-inch rebars with yellow plastic caps marked:

"Jackson C.S."

- ▶ N68°10'W, 73.96 feet, set 29 inches in the ground and located 6 feet west of guard rail at the shoulder (sub-grade) of road slope into Applegate Lake.
- ▶ S68°10'E, 46.27 feet, set 20 inches in the ground and located 21 feet East (near end) of old road C. S30°E.
- The center of light above metal door into top of Applegate dam intake structure bears N69°11'W.

Corner lies at top of cut bank of Squaw Lakes Road about 80 feet East of location marker on steel fence post attached to guard rail.

July 21, 1982
R. Frost
R. Templin
Witness: T. Newcomb

Edward McGinty
County Surveyor

V = 19°

P.-104

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 100200

Section corner common to Sections 30 and 31, Township 40 South, Range 3 West and Sections 25 and 36, Township 40 South, Range 4 West, W.M.

At the corner, found flush with the ground, the 3-inch diameter standard Bureau of Land Management brass cap marked:

T40S	
R4W	R3W
S25	S30

S36	S31
1964	

From which;

Bearing tree marked by the BLM in 1964 found,

- Douglas Fir rotted stump bears record $S01^{\circ}E$, distance not measured.

Second Re-establishment, dated 1982, references found,

- 5/8 ins. diam. rebar, no cap, bears $S68^{\circ}22'03''E$, 46.28 feet. Record $S68^{\circ}10'E$, 46.27 feet.
- 5/8 ins. diam. rebar, no cap, bears $N68^{\circ}24'55''W$, 74.16 feet. Record $N68^{\circ}10'W$, 73.96 feet.

Set new reference,

- 5/8 x 24 ins. rebar with 2 ins. diam. aluminum cap marked "Jackson County Surveyor" ,located 4 feet West of guardrail along West side of road, bears $S59^{\circ}38'33''W$, 132.79 feet.

Corner is located at the top of steep cut-bank and approx. 68 feet East of guard rail on the West side of Squaw Lakes Rd.

October 11, 2017

B. Paull

Transcribed from field notes,

S. Beecher July 7, 2019

Scott D. Fein

Jackson County Surveyor

P. -