

## FIRST RE-ESTABLISHMENT

### GCDB 100100

Township corner common to Section 36, Township 32 South and Section 1, Township 33 South, Range 2 West and Section 31, Township 32 South and Section 6, Township 33 South, Range 1 West, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1965, marked:

T32S	
R2W	R1W
S36	S31
— —	
S1	S6
T33S	
1965	

Single remaining original bearing tree recorded by Nathaniel Ford of the GLO in 1855,

- A burnt fir snag with axe work, brs. record N 50° E, 13.2 ft. to estimated face.

Bearing trees recorded by the BLM in 1965, found with healed single blazes and measured to center at base:

- D. Fir, now 52 ins. diam. brs. record; N 42° E, 64.7 ft.
- D. Fir, dead and down, brs. record; S 13° E, 42.2 ft. to center of root hole.
- Fir snag 20 ins. diam. brs. record; N 17° W, 40.9 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 15 ins. diam. brs. N 10° E, 7.8 ft.
- D. Fir 15 ins. diam. brs. S 33½° E, 28.3 ft.
- No trees available in west quadrants due to clear-cut.

Corner lies approx. 650 ft. southerly along old, blocked logging road, then approx. 400 ft. west on 60% slope.

March 2, 2011

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 33

V. – 14°20'