

## FIRST RE-ESTABLISHMENT

GCDB 100300

Section corner common to Sections 24 and 25, Township 32 South, Range 2 West and Sections 19 and 30 Township 32 South, Range 1 West, W.M.

Found the basalt stone marked with notches as described in the original notes. Said stone has been dislodged and rolled down the side of mountain.

Set a 1" x 36" galvanized iron pipe 32" in the ground with a 2½" bronze cap and placed said stone on West side of pipe. Cap stamped:

T32S R1 & 2W	
Section Cor.	
24	19
----- C.S.	
25	30
1964	

From which:

- The original bearing tree, (now a 26" Fir, plainly scribed for Section 24), bears N41°W, 29.0 feet to the face of the upper blaze;
- The original bearing tree (now a Fir stump) bears S40°W, 6.6 feet.

Marked new trees as follows:

- An 8" Fir scribed "CS-BT" bears N25°W, 46.6 feet to face of lower blaze;
- A 12" Fir scribed "CS-BT" bears S31½°E, 40.4 feet to the face of the upper blaze;
- A 6" Yew scribed "CS-BT" all on a single blaze bears N10°E, 61.1 feet to the face of the blaze;
- A 10" Fir scribed "CS-BT" bears S52½°W, 50.2 feet to the face of the lower blaze.

June 25, 1964

L. D. Pinkham, Deputy County Surveyor

Lloyd Hart

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

### GCDB 100300

Section corner common to Sections 19 and 30, Township 32 South, Range 1 West and Sections 24 and 25, Township 32 South, Range 2 West, W.M.

Found projecting 6 inches, the 1-inch diameter galvanized iron pipe with 2½-inch diameter brass cap marked:

T32S R1 & 2W	
Section Cor.	
24	19
C.S.	
25	30
1964	

As recorded on First Re-establishment, page 5, in 1964.

Original bearing trees recorded by R. Moore in 1883, found:

- Rotted, fir stump remains found at record location of southwest bearing tree.
- White Fir, 25-inch diameter, with illegible scribe marks in exposed upper face bears N41°W, 29.04 feet on slope to scribed upper face. Re-measured (horizontal distance): 28.80 feet to scribed face; 29.10 feet to center of tree at lower blaze.
- The Northeast and Southeast bearing trees are now gone.

Bearing trees marked on First Re-establishment found:

- Yew, 8-inch diameter with partly exposed (upper) single face bears N10°E, 61.3 feet to said face. Re-measured 61.6 feet to center of tree at (single) blaze. Record: 61.1 feet. **Note:** This tree is curved below blaze to base.
- White Fir, 17-inch diameter, with healed blazes bears S31½°E, 40.50 feet to center of tree at lower blaze. Record: 40.4 feet. **Note:** This tree was also single blazed on Survey No. 4344, but no scribe marks are discernible in exposed face.
- The center of the rotted stump of a down fir, 13-inch diameter scribed "BT" bears S53°W, 50.1 feet. Record: S52½°W, 50.2 feet.
- White Fir, 16-inch diameter, with healed blazes bears N25°W, 46.94 feet to center of tree at lower blaze. Record: 46.6 feet.

Marked (knife-scribed) a new tree "CS" "BT":

- Cedar, 5-inch diameter bears S24°W, 27.50 feet to center of tree at lower blaze.

Bearing trees marked on Survey No. 4344, to reference a set monument (noted below) found and measured to center of tree(s) at base:

- Cedar, 31-inch diameter, scribed "T32SR1W S19BT" in exposed single face bears N24°E, 48.7 feet.
- Douglas Fir, 37-inch diameter, with partly healed single blaze bears S22½°W, 53.16 feet.
- The Southeast (First Re-establishment) bearing tree, previously described was reported on Survey No. 4344 as reference to the below described monument:

(SECOND RE-ESTABLISHMENT CONTINUED ON NEXT PAGE)

**SECOND RE-ESTABLISHMENT (Cont.)**

**GCDB 700300**

A found 2-inch diameter galvanized iron pipe, set on the above-noted survey, projecting 19 inches, with 3-inch diameter brass cap marked:

THE OFFICIAL MONUMENT!	T32SR1-2W, W.M.	
	SEC	COR
	S29	19
	-----	
	S25	30

1970  
OPE 4906

**See Jackson County Project File 86-65.**

Corner lies on (25%) Northeast slope approximately 55 feet North of ridge top.

July 31, 1986  
R. Frost  
T. Newcomb

Edward McGinty  
County Surveyor

V = 18¼°