

FIRST RE-ESTABLISHMENT

GCDB 400200

Section corner common to Sections 27, 28, 33 and 34, Township 32 South
Range 1 West, W.M.

From the following evidence, set a 1x36-inch galvanized iron pipe with 2½-inch diameter brass
cap marked:

T32S R1W	
28	27
33	34
C S	
1990	

Cemented in the top protruding 6 inches aboveground.

Original bearing trees marked by R. Moore in 1883 found (the original stone could not be found):

- Douglas Fir, 10-inch diameter, with scribe marks visible in a partially healed upper blaze bears Record: N73°E, 29.04 feet to exposed face.
- Douglas Fir, 31-inch diameter, with healed upper blaze and "BT" bark scribed lower face bears Record: S62°E, 56.76 feet to estimated upper face. Record distance 58.08 feet.
- Douglas Fir snag, 17-inch diameter, with T32S R1W S33 scribing visible in a partially healed upper blaze bears Record: S58°W, 33.66 feet to exposed face. This tree has North-South line blazed through it.
- Douglas Fir snag, 50-inch diameter, with bark scribing T32S R1W S28 BT visible on a double blaze bears Record: N55°W, 9.0 feet to lower face.

Marked new trees "CS" "BT" and measure to the center of tree at lower blaze:

- Douglas Fir, 23-inch diameter bears S41½°W, 45.93 feet.
- Douglas Fir, 17-inch diameter bears N89½°W, 53.00 feet.

Corner lies on Northeast slope in virgin timber approximately 500 feet North of ridge top.

January 24, 1990
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 16°

P. -21