

## FIRST RE-ESTABLISHMENT

GCDB 400240

Quarter corner common to Sections 27 and 28, Township 32 South, Range 1 West, W.M.

From the following evidence, set a 1 x 36-inch galvanized iron pipe set 30 inches in the ground, with a 2½-inch diameter brass cap marked:

T32S R1W  
¼S  
28 | 27  
C.S.  
1992

Original stone gone.

Original bearing trees recorded by R. S. Moore in 1883 found:

- Douglas Fir, 24-inch diameter, with healed blazes bears N18°W, 7.26 feet to estimated face. Record: 3.30 feet. Re-measured 7.72 feet to center of tree at lower blaze.
- Douglas Fir, 23-inch diameter, opened upper blaze containing scribe mark "s" bears N55°E, 3.30 feet to upper face. Record: 7.26 feet. Re-measured 3.78 feet.

Marked new tree "CS" "BT":

- Douglas Fir, 14-inch diameter bears N76½°E, 45.88 feet to the center of tree at lower blaze.
- Set a concrete nail and shiner in rock face bears N84°W, 4.70 feet.

Corner lies on steep and rocky North slope. Posted location tag on a 20 inches Fir south at top of ridge course SE-NW about 400 feet.

August 25, 1992  
T. Newcomb, Tech.  
D. Thompson

Verlyn Thomas  
County Surveyor

V = 19¾°

P. -74