

FIRST RE-ESTABLISHMENT  
GCDB 440400

SPECIAL CORNER

Quarter corner common to Sections 15 and 22, Township 32 South, Range 1 West, W.M.

Found at the proportioned position, exposed 12 ins. in a mound of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the BLM in 1955, marked:

T32S R1W  
S15  
¼—  
S22  
1955

Bearing trees recorded by the BLM in 1955, found with healed single blazes and measured to center at base:

- Sawed rotted Fir stump 50 ins. diam. brs. record; N 55½° E, 122.8 ft.
- W. Fir, now 35 ins. diam. brs. record; S 39¼° E, 20.5 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 8 ins. diam. brs. S 68° W, 12.1 ft.
- D. Fir 12 ins. diam. brs. N 20½° W, 23.9 ft.
- No trees practical in northeast quadrant.

Corner lies approx. 300 ft. north of a "Y" intersection old dirt roads that run along ridge top.

May 22, 2012  
H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 190  
V. – 15°25'