

## FIRST RE-ESTABLISHMENT

GCDB 540500

Quarter corner common to Sections 11 and 14, Township 32 South, Range 1 West, W.M.

Found at the corner position, exposed 6 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by Douglas County in 1968, marked:

COUNTY SURVEYORS OFFICE  
T32S R1W  
S11  
¼  
S14  
1968

Original bearing trees recorded by Rufus Moore of the GLO in 1883, found and measured to center at base:

- D. Fir, now 33 ins. diam. with healed blazes, brs. record; N 45° W, 4.6 ft.
- D. Fir, dead and down with scribed marks "¼S" "BT" in partially healed blazes, brs. S5°W, 16.0 ft. to center of stump hole. Record; 13.2 ft. to face.

Bearing tree recorded by Douglas County in 1968,

- A Fir snag 21 ins. diam. with a rotted face, brs. record; S59°W, 18.3 ft. to center at base.

Bearing tree recorded by Gerald Nygren in 1989,

- A W. Fir 8 ins. diam. with healed double blazes, brs. record; S59°E, 35.1 ft. to center at base.

Bearing tree recorded on Survey No. 17978 in 2003,

- A W. Fir 7 ins. diam. with a mostly healed single blaze, brs. N40¼°E, 18.6 ft. to center at base. Record, N42¼°E.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. Fir 9 ins. diam. brs. S49½°W, 16.3 ft.

Corner lies approx. 300 ft. east of old 4-wheel-drive road.

June 20, 2012

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 205  
V. – 14°