

## FIRST RE-ESTABLISHMENT

GCDB 540600

One Quarter corner common to Sections 2 and 11, Township 32 South, Range 1 West, W.M.

From the following original evidence at the location described below, set a 2x32-inch galvanized iron pipe 28 inches in the ground, for the corner, with a 2½-inch diameter brass cap marked:

T32S R1W  
2  
¼S —  
11  
C.S.  
1981

Original bearing trees recorded by R. Moore in 1883, found as follows:

- Rotted Fir stump remains with portions alongside containing old axe work and scribed (partial) "BT" bears Record: S20°W, 3.30 feet to estimated original position of scribed face.
- Rotted Fir root and stump remains, containing old axe work, found at record location of original Northwest bearing tree.
- The original stone is now gone.

**SEE also** Jackson County field notes, page 73-74, dated 5/7/81.

A found 2-inch diameter aluminum pipe, projecting 5 inches with aluminum cap marked:

T32S R1W W.M.  
2  
¼S —  
11  
1980  
PLS 1035

Set by proportionate method, on Survey No. 8498, dated 1980 bears S86°24'E, 48.75 feet.

Mound stones around corner, marked new trees "CS" "BT," and took measurements to center of trees at lower blaze:

- Douglas Fir, 9-inch diameter bears S27°54'W, 17.00 feet (5.18 m).
- Hemlock, 13-inch diameter bears N63°50'W, 21.10 (6.43 m).

Corner lies on steep (90%) North slope an estimated 400 feet North of road along top of Umpqua Divide ridge top.

May 7, 1981

R. Frost

R. Templin

Witness: T. Newcomb, USFS

Edward McGinty

County Surveyor

P. 73-74