

FIRST RE-ESTABLISHMENT

GCDB 600200

Section corner common to Sections 25, 26, 35 and 36, Township 32 South, Range 1 West, W.M.

Found projecting 6 inches in mound of stone, a 2-inch diameter galvanized iron pipe, with 3¼-inch diameter standard BLM brass cap marked:

T32S R1W	
S26	S25

S35	S36
1965	

Bearing trees marked by BLM in 1965 found:

- Yew, now dead, 13-inch diameter scribed T32SR1W S36 BT" in unhealed single blaze bears S75°E, 55.71 feet. Record: 56.76 feet.
- Fir stump, 20-inch diameter, with healed blaze bears S3°W, 39.22 feet. Record: 39.60 feet.
- Fir stump, 13-inch diameter bears N60°W, 28.48 feet. Record: 27.06 feet.
- A bearing tree marked on Survey No. 2738 dated 1964; a Maple, now 12-inch diameter, with healed blazes bears N20°W, 5.20 feet. Record: N25°30'W, 14.85 feet.
- Other bearing trees of record are now either tipped over or gone.

Marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir, 17-inch diameter bears N17°E, 83.35 feet.
- Douglas Fir, 49-inch diameter bears S29½°E, 28.34 feet.
- Douglas Fir, 9-inch diameter bears S67°W, 27.40 feet.

Corner lies an estimated 20 feet South of draw c. N75°W, 60 feet East of creek and about 300 feet, S85°W of location marker on 4-inch diameter fir alongside road c. Northwest and South.

February 5, 1987

R. Frost

T. Newcomb

Edward McGinty

County Surveyor

V = 19°

P. -31