

FIRST RE-ESTABLISHMENT

GCDB 600500

Section corner common to Sections 11, 12, 13 and 14, Township 32 South, Range 1 West, W.M.

From the following original evidence, at the location described below, set a 2x32-inch galvanized iron pipe, 26 inches in the ground, with a 2½-inch diameter brass cap marked:

T32S R1W	
11	12
14	13
C.S.	
1981	

Original bearing trees recorded by R. Moore in 1883, found:

- Douglas Fir, 12-inch diameter, scribed "32SR1W" in partly opened face bears Record: S39°E, 25.08 feet to scribed face.
- Douglas fir, 22-inch diameter, with healed blazes bears S18°W, 9.24 feet to estimated face. Record: S22°W. Re-measure 9.74 feet to center of tree at lower blaze.
- Original stone is now gone.

Mounded stones around corner and mk. new trees "CS" "BT," and took measurements to center of trees at lower blaze:

- Fir, 13-inch diameter bears N30°05'E, 24.68 feet (7.52 m)
- Fir, 15-inch diameter bears N20°10'W, 29.00 feet (8.84 m)

Corner lies on Northeast slope about 300 feet South of location marker on 16-inch diameter Fir, located on point of ridge approximately 150 feet North of road.

June 15, 1981
R. Frost
R. Templin
Witness: T. Newcomb

Edward McGinty
County Surveyor

V. -20½°

P. -94