

FIRST RE-ESTABLISHMENT

GCDB 640500

Quarter corner common to Sections 12 and 13, Township 32 South, Range 1 West, W.M.

Found at the corner, projecting 18 inches, a 1-inch diameter iron pipe with a 2-inch diameter pot metal filled reducer marked:

12
¼S —
13
T32S R1W

With the original stone found alongside.

Replaced said iron pipe with and deposited it alongside a 1-inch diameter, 36-inch long galvanized iron pipe, set 30 inches in ground with a 2½-inch diameter bronze cap marked:

JACKSON COUNTY 1981
T32S R1W
12
¼S —
13

From which original bearing trees recorded by R. Moore in 1883, found as follows:

- Douglas Fir (dying), 17-inch diameter containing scribe mks in partially open upper face (tree tipped northerly) bears N38°E, 6.50 feet to scribed face. Record: 4.62 feet.
- Douglas Fir stob, 17-inch diameter, scribed "¼S" "BT" in exposed faces bears Record: S47°E, 5.28 feet to scribed face.

Marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir, 7-inch diameter bears S70°E, 33.35 feet (10.16 m).
- Hemlock, 6-inch diameter bears S13°W, 50.65 feet (15.43 m).

Corner lies about 50 feet south of draw c. N70°E and 300 feet East of location marker on 12-inch diameter fir alongside road.

See also Survey No. 534.

See also Survey No. 4976.

June 23, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

P.-98