

FIRST RE-ESTABLISHMENT

GCDB 700140

Quarter Section corner on Willamette Meridian - Section 36, Township 32 South Range 1 West and Section 31, Township 32 South, Range 1 East.

Found the original BT to the Southwest, now a 26" alder with scribe legible, from which:

Set a 1" x 36" galvanized iron pipe 30" in the ground with a 1½" expander filled with pot metal and stamped

T 32S R 1 W R 1 E 36+31CS-1954

Screwed on top of said pipe for corner;

- Scribe a 44" cedar CS-BT which bears North 67° West 23.5 feet;
- Scribe a 19" Douglas fir CS-BT which bears North 41½° East 41.0 feet.

Corner falls in the South Fork of Alco Creek.

November 10, 1954

C. Z. Boyden

John L. Gartman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700140

Quarter corner common to Section 31, Township 32 South, Range 1 East and Section 36, Township 32 South, Range 1 West, W.M.

Found projecting 6 inches the 1-inch diameter iron pipe with 2½-inch diameter post metal filled pipe reducer marked:

T32S
CS 36 | 31 1954
R1W | R1E
W.M.

Original bearing trees are now gone.

Bearing trees marked on First Re-establishment, Page 1 in 1954, found as follows:

- Douglas Fir, 29-inch diameter with healed blazes bears Record: N 41½° E, 41.70 feet to center of tree at lower blaze.
- Tipped over cedar, about 48-inch diameter, lying (face) alongside corner bears Record: N 67° W, 23.5 feet to base.

Mark a new tree, "CS "BT":

- Douglas Fir, 27-inch diameter bears N 22° W, 9.00 feet to center of tree at lower blaze.

Corner lies an estimated 62 feet South of Alcoa Creek and S 44° W, about 195 feet from location marker on 48-inch diameter cedar alongside road, c. North and Southeast.

February 4, 1987

R. Frost

T. Newcomb

Edward McGinty

Jackson County Surveyor

V = 20½°

P. -31

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT


THIRD RE-ESTABLISHMENT

GCDB 700140

Quarter corner common to Section 36, Range 1 West and Section 31, Range 1 East of Township 32 South, W.M.

Found at the corner position, exposed 10 inches, the 1-inch diameter galvanized iron pipe with 2½-inch diameter pot metal filled reducer (pot metal now melted out) set on First Re-establishment in 1954.

Broke reducer off and cemented in top of said 1-inch diameter pipe, a 2½-inch diameter brass cap marked:



Monument is now exposed 6 inches and in a mound of stones.

Bearing trees recorded on Second Re-establishment in 1987, found and measured to center of tree at lower blaze unless otherwise noted:

- Fir snag 30-inch diameter and burnt with healed blazes bears Record: N 41½° E, 41.70 feet.
- Down cedar snag 40-inch diameter bears Record: N 67° W, 23.5 feet to center of large stump hole.
- Down Douglas fir 30-inch diameter bears Record: N 22° W, 9.00 feet to center of stump hole.

Set new references, 5/8 x 30-inch rebar exposed 0.4 feet with 1½-inch diameter aluminum caps marked:

JACKSON COUNTY
●
SURVEYOR

- N 70½° W, 37.7 feet.
- S 69° W, 32.20 feet.
- S 24° W, 19.65 feet.

Set fence posts by new references and corner monument.

Corner lies near bottom of easterly drainage c.-N 75° E, and approximately 180 feet westerly of road.

December 2, 2002

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. -210

V. -17°