

## FIRST RE-ESTABLISHMENT

GCDB 700200

Section corner common to Sections 25 and 36, Range 1 West and Sections 30 and 31, Range 1 East of Township 32 South, W.M.

Found, at the corner position, exposed 8 inches, the 2-inch diameter galvanized iron pipe with 2½-inch diameter brass cap set by the BLM in 1968, marked:

T32S	
R1W	R1E
S25	S30
— —	
S36	S31
1968	

Bearing trees, recorded by the BLM in 1968, found with healed single blazes and measured to center of trees at base:

- Douglas Fir 20-inch diameter bears Record: N 12° W, 21.78 feet.
- Douglas Fir 12-inch diameter bears S 43° W, 12.20 feet. Record: 12.54 feet.

Marked new bearing trees "CS" "BT" and took measurements to center of tree at lower blaze:

- Douglas Fir 16-inch diameter bears S 16½° E, 12.5 feet.
- Douglas Fir 13-inch diameter bears N 7° E, 42.5 feet.

Corner lies 5 feet westerly from top of cut bank and approximately 20 feet westerly from center of road.

October 30, 2002

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. -209

V. -14½°