

FIRST RE-ESTABLISHMENT

GCDB 100140

Quarter corner common to Section 36, Township 32 South, Range 3 East and Section 31, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T32S
R3E R4E
¼
S36 | S31
1966

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883,

- Rotted remains of a Fir stump, brs. record; S 75° E, 26.4 ft. to center of remains.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- D. Fir, now 25 ins. diam. brs. N 41¼° E, 17.8 ft. Record; N 40° E.
- D. Fir, now 22 ins. diam. brs. record; S 33° W, 53.5 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Mad. 15 ins. diam. brs. S 70° E, 7.8 ft.
- D. Fir 5 ins. diam. brs. N 65¾° W, 17.8 ft.

Corner lies approx. 220 ft. east of bend in gravel road.

June 22, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 101

V. – 17°