

FIRST RE-ESTABLISHMENT

GCDB 100300

Section corner on the Range line to Sections 24 and 25, Township 32 South, Range 3 East and Sections 19 and 30, Township 32 South, Range 4 East.

Found the N.W. and S.W. BTs intact with scribing plainly visible in both trees.

From this evidence, set a 2"x36" galvanized iron pipe, 33 " in the ground for corner.

From which:

- The original BT (Now a 16" Fir) bears N14°W, 12.5 feet;
- The original BT (Now an 18" White Fir) bears S30°W, 33.0 feet;
- A 16" White Fir scribed "CS-BT" bears S54°E, 34.3 feet;
- An 8" White Fir scribed "CS-BT" bears N85°E, 19.5 feet.

July 10, 1950
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 100300

Section corner on the range line between Sections 24 & 25, Township 32 South, Range 3 East and Sections 19 & 30, Township 32 South, Range 4 East.

Found the 2"x36" galvanized iron pipe corner monument, the original NW BT with scribe marks legible and the 9" White Fir NE BT as reported in the first renewal on July 10, 1950.

Drove a 1"x36" galvanized iron pipe in side of said 2" pipe for corner. On top the 1" pipe, set the standard 2½" bronze cap stamped:

"T32SR 3/4E CS 1961 24/19 25/30"

From which,

- The original BT (now a 16" Douglas Fir) with the scribe legible bears North 13° West, 12.6 feet to the face of the old scribe;
- The first renewal BT, a 9" White Fir intact bears North 86° East, 19.5 feet to the old blaze;
- The center of a 12" White Fir, scribed "CS-BT" bears South 46½° West, 53.0 feet;
- The center of a 7" Hemlock, scribed "CS-BT" bears South 64° East, 67.7 feet.

October 5, 1961

C. Z. Boyden

John Gartman