

FIRST RE-ESTABLISHMENT

GCDB 100700

Township corner common to Townships 31 and 32 South, and Ranges 3 and 4 East, W.M.

Found at the corner position, exposed 4 ins. in a mound of stones, the 3 ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the GLO in 1937, marked:

T31S
F3E R4E
S36 | S31
—+—
S1 | S6
T32S
1937

Original bearing trees recorded by the GLO in 1937, found with healed blazes and measured to center at base:

- Rotted Fir snag brs. N 11° E, 19.1 ft. record; N 9° E.
- W. Fir, now 34 ins. diam. brs. S 26¼° E, 29.0 ft. Record; S 25° E.
- D. Fir, now 21 ins. diam. brs. S 62¼° W, 34.3 ft. record; S 61° W.
- D. Fir, now 30 ins. diam. brs. record; N 49° W, 52.8 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Easterly branch of a forked Yew 5 ins. diam. brs. N 44¼° E, 7.2 ft.

Corner lies approx. 450 ft., N 45° W of a gravel road.

September 29, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 60

V. – 16°30'