

FIRST RE-ESTABLISHMENT

GCDB 140500

Quarter corner common to Sections 7 and 18, Township 32 South, Range 4 East, W.M.

Found firmly set, the original 14x10x9-inch (36x25x23 cm), Record: 14x14x10-inch (36x36x26 cm) stone, marked: "¼" on North face.

I replaced said stone with a 1x36-inch (2.5x91 cm) Galvanized iron pipe set 30 inches (76 cm) in the ground with a 2½-inch (6.4 cm) bronze disc marked:

JACKSON COUNTY 1978
T32S R4E
7
¼S —
18

Original bearing trees recorded by R. Moore in 1884 found as follows:

- Rotted fir stump remains bear Record: S75°E, 7.26 feet (2.21 m).
- The base and root hole of a tipped out fir stump, 18 inches (46 cm) diameter bears Record: N30°W, 7.26 feet (2.21 m).

I mounded stones around corner, marked new trees CS BT, and took measurements to center of trees at lower blaze:

- White fir, 11-inch (28 cm) diameter bears N8½°E, 35.1 feet (10.70 m).
- Douglas fir, 9-inch (23 cm) diameter bears S43½°E, 13.04 feet. (3.97 m).

Corner lies on gentle (15%) South slope about 200 feet (61 m) North of steeper (40%) South slope and approximately 450 feet (137 m) North of location marker on 16 inches (41 cm) diameter fir located alongside road ©. S75°W) at top of cut bank.

October 24, 1978

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor