

## FIRST RE-ESTABLISHMENT

GCDB 200200

Section corner common to Sections 29, 30, 31, 32, Township 32 South, Range 4 East.

Found mound of stone at the corner from which the original BT to the NE checks OK. Also found the BTs to the SE and NW down with scribes visible.

From this evidence, set a 2"x36" galvanized iron pipe 32" in the ground for corner.

From which:

- The original BT, now a 22" White Fir with lower blaze intact bears N.5°E., 5.94 feet;
- A 7" Yew, scribed "C.S.-BT" on one blaze bears N. 8° W. 18.8 feet;
- A 9" White Fir, scribed "C.S.-BT" bears S. 30½° W., 18.7 feet;
- A 6" White Fir, scribed "C.S.-BT" bears S. 68° E., 18.5 feet.

June 29, 1950

C. Z. Boyden

L. D. Pinkham

A. W. Holmes, Present

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 200200

Section corner common to Sections 29, 30, 31 and 32, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 6 inches and in a mound of stones, the 2½-inch diameter galvanized iron pipe with a 3½-inch diameter brass cap set by the BLM in 1966, marked:

T32S	R4E
S30	S29
-----	
S31	S32
1966	

Bearing trees recorded by the BLM in 1966, found and measured to center of trees at base:

- Sawed, rotted fir stump bears Record: N 65° E, 61.4 feet.
- Yew, now 16-inch diameter with partially healed single blaze revealing scribe marks "T32S R4E S30 BT" bears Record: N 58° W, 43.9 feet.

Marked new bearing trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir 8-inch diameter bears S 40½° E, 11.2 feet.
- Douglas Fir 8-inch diameter bears N 53° E, 21.7 feet.
- White Fir 7-inch diameter bears S 88° W, 32.0 feet.

Corner lies approximately 2000feet southerly from end of spur road with a steel fence post and sign 1 foot north.

June 18, 2007

H. Durkee  
B. Beeman

Roger R. Roberts  
Jackson County Surveyor

P. - 138  
V. - 15°30'