

FIRST RE-ESTABLISHMENT

GCDB 200400

Section corner common to Sections 17, 18, 19 and 20, Township 32 South, Range 4 East, W.M.
 $V = 20^\circ$

Found firmly set the original 18x12x9-inch (46x30x23 cm) Record: 20x12x8-inch (51x30x20 cm) stone, marked with 5 grooves on the East and 3 on the South.

I replaced said stone with a 1x36-inch (2.5x91 cm) Galvanized iron pipe set 30 inches (76 cm) in the ground with a 2½-inch (6.4 cm) bronze disc marked:

Jackson	
County	
1978	
T32S R4E	
18	17
19	20

Original bearing trees recorded by R. Moore in 1884 found as follows:

- The base and stump remains of a down, burned and rotted fir of undetermined diameter bears Record: $N38^\circ E$, 10.56 feet (3.22 m).
- Root hole found at record location of original SW BT.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas fir, 10-inch (25 cm) diameter bears $N45\frac{1}{2}^\circ E$, 27.33 feet (8.33 m).
- Douglas fir, 22-inch (56 cm) diameter bears $S41\frac{1}{2}^\circ E$, 13.50 feet. (4.11 m).
- Douglas fir, 13-inch (33 cm) diameter bears $S40^\circ W$, 7.60 feet. (2.32 m).
- Douglas fir, 18-inch (46 cm) diameter bears $N28^\circ W$, 25.70 feet. (7.83 m).

Corner lies about 600 feet (183 m) South of road.

October 19, 1978

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor