

**FIRST RE-ESTABLISHMENT**

**GCDB 340300**

Quarter corner to Sections 21 and 28, Township 32 South, Range 4 East.

Found mound of stone at the corner together with the two original Chinquapin BTs, dead with scribe legible in both trees, which evidence agrees with the official Govt. record.

Set a 1"x34" iron pipe 30" in the ground for corner.

From which:

- A 20" White Fir, scribed C.S.-BT bears N.  $41\frac{1}{2}^\circ$  E., 26.9 feet;
- A 16" White Fir, scribed C.S.-BT (on one blaze) bears S.  $37\frac{1}{2}^\circ$  E, 29.5 feet;
- The center of a 52" Douglas Fir (not scribed) bears S.  $82^\circ$  W., 19.5 feet.

Var.  $19^\circ$  E.

June 29, 1950

C. Z. Boyden

L. D. Pinkham

A. W. Holmes, Present

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

**SECOND RE-ESTABLISHMENT  
GCDB 340300**

Quarter corner common to Sections 21 and 28, Township 32 South, Range 4 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T32S R4E  
S21  
¼—  
S28  
1966

Bearing trees recorded on 1<sup>st</sup> Re-establishment in 1950, found with healed blazes and measured to center at base:

- W. Fir, now 35 ins. diam. brs. record; N 43° E, 27.7 ft.
- W. Fir, now 31 ins. diam. brs. record; S 34° E, 30.4 ft.

Bearing tree recorded by the BLM in 1966, found with a healed single blaze and measured to center at base:

- W. Fir, now 27 ins. diam. brs. record; S 3° E, 52.3 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 8 ins. diam. brs. S 52½° W, 16.8 ft.
- W. Fir 7 ins. diam. brs. N 61½° W, 14.6 ft.

Corner lies approx. 100 ft. west of gravel spur road.

July 5, 2011  
H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 1  
V. – 16°40'