

FIRST RE-ESTABLISHMENT

GCDB 400300

Section corner of Sections 21, 22, 27 and 28, Township 32 South, Range 4 East, W.M. $V = 21\frac{1}{4}^\circ$

Found the single remaining original bearing tree, recorded by R. Moore in 1884, now a down and rotted chinquapin, containing reverse impression of scribe marks including "S2" and "BT" in partly decayed (reverse) faces.

From the preceding evidence, I set a 1x36-inch Galvanized iron pipe, 30 inches in the ground with a 2½-inch bronze disc marked:

Jackson	
County	
1978	
T32S R4E	
21	22
28	27

From which:

- The rotted stump, about 8-inch diameter, of the above-described original bearing tree bears Record: N13°E, 19.14 feet.
- Original stone not found.

I mounded stones around corner, marked the following trees "CS-BT," and took measurements to center of trees at lower blaze:

- Douglas fir, 29-inch diameter bears N46½°E, 6.26 feet
- White fir, 15-inch diameter bears S5°E, 54.89 feet.
- White fir, 31-inch diameter bears S58°W, 13.68 feet.
- White fir, 25-inch diameter bears N9°W, 38.26 feet.

Corner lies on (original) N-S blazed line, about 350 feet North of draw C. NW.

October 12, 1978

B. Malotte

R. Frost

Witness: T. Newcomb, USFS

Approved by: Edward McGinty
County Surveyor