

FIRST RE-ESTABLISHMENT

GCDB 427100

Standard Section corner common to Sections 33 and 34, Township 32 South, Range 4 West, W.M.

Found:

- No trace of Northwest BT.
- 18-inch Douglas Fir, now dead stob, N45°E, 12.5 feet, upper face open, old rotten scribe visible, "S" & other marks.

Set Brass cap at corner mkd:

County Surveyor's	T32S	Doug. Co.
Office	R4W	S33 S34
1970		— —
	T33S	S SC
		Jack. Co.

New BTs:

- 24-inch Douglas Fir N48°E, 19.5 feet mkd: "T32S R4W S SC S34 CS BT".
- 32-inch Douglas Fir N8°W, 21.4 feet mkd: "T32S R4W S SC S33 CS BT".

This corner lies approximately 125.0 feet West of draw.

May 19, 1970

W. Penley & J. Heritage (Doug. Co.)