

FIRST RE-ESTABLISHMENT

CLOSING CORNER TO SECTIONS 34 AND 35 ONLY

GCDB 500100

Closing corner common to Sections 34 and 35, Township 32 South, Range 4 West, W.M.

The Southwest Section Corner of Section 35, Township 32 South, Range 4 West was a stone which has been destroyed by a cat fire trail on a BLM timber sale.

I replaced the corner as follows:

- Set 1x30-inch iron pipe, 10 inches above ground level.
- Used compass and steel tape.

Two original bearing trees remain:

- 24-inch Douglas Fir bears 96 links distance
- 30-inch Douglas Fir bears 50 links distance

July 32, 1968
Loren Swearingen