

FIRST RE-ESTABLISHMENT

GCDB 100340

Quarter corner common to Section 24, Township 34 South, Range 2 West, and Section 19, Township 34 South, Range 1 West, W.M. $V = 18\frac{3}{4}^\circ$

From the following evidence at the location described below, I set a 1x36-inch G.I. pipe 22 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1975
T34S
¼S 24 | 19
R2W R1W

- The stump of a down and rotted Black Oak, 8-inch diameter, containing reverse impression of scribed "1" bears Record: N22°E, 16.50 feet to estimated face.
- A Laurel, 30-inch diameter, severely burned with upper face axed out bears Record: S58°W, 12.54 feet to estimated face.
- Found, (Elk Lumber Co.) 1-inch diameter G.I. pipe, projecting 12 inches with attached 2-inch diameter pot metal (unmarked) filled reducer.
- I stamp the above "C.S. R.P. 1975" which bears N64½°E, 9.2 feet to punch Mark on Westerly side.

A 1x36-inch G.I. pipe, with metal filled reducer, marked:

T34S R1 & 2W
+
¼ Cor 24-19
1960

found inside the afore-mentioned Madrone BT.

I marked the following trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 7-inch diameter, bears N11°E, 101.7 feet.
- Black Oak, 12-inch diameter, bears S79°W, 46.2 feet.

August 5, 1975
Ed Graham
K. Weaver

Approved by: Edward McGinty
County Surveyor