

## FIRST RE-ESTABLISHMENT

GCDB 100700

Township corner common to Section 36 in Township 33 South, Range 2W, Section 31 in Township 33 South, Range 1 West, Section 1 in Township 34 South, Range 2W, and Section 6 in Township 34 South, Range 1 West, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. galv. iron pipe with the 3½ ins. diam. brass cap set by the BLM in 1973, marked:

T33S  
R2W R1W  
S36 | S31  
—+—  
S1 | S6  
T34S  
1973

Bearing trees recorded by the BLM in 1973, found with healed single blazes and measured to center at base:

- Fir, 23 ins. diameter bears record N55°E, 38.48 ft. Record: 59½ lks.
- Fir, 19 ins. diameter bears record S57°W, 49.70 ft. Record: 75½ lks.
- Fir Stump bears record S68°E, 14.85 ft. Record: 23 lks.
- Fir Stump bears record N72°W. Not measured due to trees on line.

Bearing tree with Jackson County bearing tree tag dated 02/2009 but unrecorded, measured to center of tree at base:

- Fir, 14 ins. diameter, with healed double blaze, bears S16°E, 24.85 ft. Record on tag, S15°E 24.7 ft.

Corner lies in wooded area, approx. 50 ft. north of gravel road, and approx. 50 east of dirt skid road.

August 22, 2016

B. Paull

Scott Fein  
Jackson County Surveyor

P. -  
V. 16°