

FIRST RE-ESTABLISHMENT

GCDB 200400

Corner to Sections 17, 18, 19, 20, Township 34 South, Range 1 West.

Found pipe near corner,

- Also the Northwest bearing tree with bearing tree scribe legible;
- The Northeast bearing tree, a stump hole;
- The Southeast bearing tree with no scribe visible;
- The Southwest bearing tree, a down pine with scribe legible;

From which evidence

- Reset a 1"x 36" galvanized iron pipe with a 1½" expander on top filled with pot metal and stamped: "T34S-R1W Section Cor. 18/17/19/20", set 30" in the ground for corner

From which:

- A 16" White Oak scribed "CS-BT" bears South 12½° East, 23.7 feet;
- Scribe a 13" White Oak "CS-BT" which bears North 21° East, 41.2 feet;
- Scribe a 5" White Oak "CS-BT" which bears North 41½° West, 36.8 feet;
- Scribe a 6" White Oak "CS-BT" which bears south 12½° West, 40.4 feet;

March 14, 1957
C. Z. Boyden
K. D. Weaver