

FIRST RE-ESTABLISHMENT

GCDB 200700

Section corner common to Sections 31 and 32 of Township 33 South, and Sections 5 and 6 of Township 34 South, Range 1 West, W.M.

Found at the corner position, flush, in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1965 and marked:

T33S R1W
S31 | S32
—+—
S6 | S5
T34S
1965

Single remaining original bearing tree recorded by Ives and Hyde of the GLO in 1854 found with a healed blaze and measured to center at base;

- B. oak now 17 ins. diam. brs. record N14°W, 60.7 ft. on the slope.

Bearing trees recorded by the BLM in 1965 found with healed single blazes and measured to center at base;

- Cedar now 16 ins. diam. brs. record N24°E, 62.7 ft on the slope.
- Fir rotted stob brs. record S37°E, 77.2 ft. on the slope.
- Fir sawed stump brs. S2°W, 45.5 ft. on the slope, record ; S3°W
- Cedar snag brs. record N65°W, 29.0 ft.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. oak 12 ins. diam. brs. S25½°E, 39.5 ft.
- P. pine 6 ins. diam. brs. S58°W, 52.0 ft.

Corner lies approx. 800 ft. easterly from BLM gate then approx. 20 ft. north.

March 23, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 62

V. – 16°