

## FIRST RE-ESTABLISHMENT

GCDB 240200

Quarter corner between Section 29 & 32. Township 34 South, Range 1 West.

Found

- Original bearing tree in Section 29, intact.
- White Oak bearing tree in Section 32 rotted down with BT marks visible.

Set corner and

- New bearing tree an 8" white oak which bears S20½°E, 53.09 feet.

April 29, 1917.  
A. T. Brown,  
County Surveyor

H. L. Speck, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 240200

Quarter corner common to Sections 29 and 32, Township 34 South, Range 1 West.

Found a 3"x3" Oak stake for corner and replaced it with a 1"x 36" galvanized iron pipe 30" in the ground with a 2½" bronze cap stamped:

T34SR1W  
29  
¼S — Cor.  
32  
C.S.  
1967

From which:

- A 26" Yellow Pine, an original bearing tree plainly scribed, bears North 20° West, 2.0 feet to the face of the lower blaze;
- A 12" White Oak, marked at the First Re-establishment, plainly scribed on a single blaze, bears South 22¼° East, 54.0 feet of the face of the blaze.

Marked the following new trees:

- An 11" White Oak, scribed CS-BT, bears South 39½° West, 20.6 feet to the face of the lower blaze;
- An 11" White Oak, scribed CS-BT, bears North 56½° West, 39.4 feet to the face of the upper blaze.

November 10, 1967  
F. A. Roberts

Approved By:  
L. D. Pinkham  
Deputy County Surveyor