

FIRST RE-ESTABLISHMENT

GCDB 300500

Corner common to Sections 8, 9, 16 and 17, Township 34 South, Range 1 West, W.M.

Found a 1" iron pipe in an old mound of stone for corner. (See Recorded Survey No. 3495)

Replaced said pipe with a 1"x 36" galvanized iron pipe set 32" in the ground with a 2½" bronze cap stamped:

T34S, R1W	
8	9
Sec.	Cor.
17	16
C.S.	
1967	

From which:

- A 16" White Oak with center rotted out behind two old faces opened before. This tree has two old cruiser's marks and a GLO tag dated 1940. Said tree bears North $59\frac{1}{2}^{\circ}$ West, 43.2 feet;
- A stump hole of a down White Oak snag with two old blazes chipped out and rotted bears South 55° East 39.5 feet.

Marked the following new trees:

- A 16" White Oak scribed CS-BT bears South $74\frac{1}{2}^{\circ}$ East, 40.2 feet to the face of the upper blaze;
- A 24" White Oak scribed CS-BT bears North $65\frac{1}{2}^{\circ}$ East, 61.2 feet to the face of the upper blaze;
- An 8" White Oak scribed CS-BT bears South $66\frac{1}{2}^{\circ}$ West 65.6 feet to the face of the upper blaze.

August 21, 1967
L. D. Pinkham,
Deputy County Surveyor

Gary Kaiser