

FIRST RE-ESTABLISHMENT

GCDB 300700

Section corner common to Sections 32 and 33, Township 33 South, Range 1 West, and Sections 4 and 5, Township 34 South, Range 1 West, W.M.

Found a 9" square by 24" high stone with cross on top for corner.

Replaced said stone with a 1"x 36" galvanized iron pipe with 2½" bronze cap and built a mound of stone around the monument as it falls on solid rock. The brass cap is stamped:

T33-34S, R1W
32 | 33
Sec ——— Cor.
5 | 4
C.S.
1972

From which:

- The original bearing tree, now a 20" Black Oak with upper face open and portion of scribing visible, bears N39°W, 86.6 feet to center (original Record: 15" Black Oak, N37°W, 84.5 feet)
- The original bearing tree, now a 30" sawed off Yellow Pine stump with BT scribe plainly visible, bears N47°E, 69.8 feet to lower face (Original Record: 16" yellow pine N48°E, 69.9 feet).
- The original bearing tree, now a 21" Yellow Pine with upper face open and scribing visible, bears S36½°E, 97.6 feet to upper face. (Original Record: 13" yellow Pine, S37°E, 97.0 feet)
- The original bearing tree, now an 8" White Oak in poor condition bears S73¼°W, 31.0 feet to center. (Original - 6" White Oak, S73°W, 30.4 feet).

Marked new trees as follows:

- A 10" Fir scribed "CS-BT" bears N26¼°E, 62.05 feet to the face of the lower blaze.
- An 11" Fir scribed "CS-BT" bears S31¼°W, 71.41 feet to the face of the lower blaze.

June 14, 1972
Lloyd Shreeve
Stephen Woodcock

Approved by: Mark E. Boyden
County Surveyor